

Factors Effecting Fatigue Life:

- mean stress *inversely pr.*
- design factors *fillets, etc.*
- surface treatment *rough surface reduces f.l*
- thermal fatigue
- corrosion

Creep: def. under elevated temp & static stress.